

SERVICE MESSAGE

WLS	_____
HLH	_____
WLS	_____
RCL	_____
RDS	R45

7 JANUARY 1948

DC/

SECRET

SECTRAF FROM

COPY #1 CCD
COPY #2 SSCS
COPY #3 OPS ✓

RE #WASH

1. REGRET NOT ANSWERING #WASH SOONER BUT STATUS

STATION UNCERTAIN HERE. WHATEVER SOLUTION CAN WORK OUT WILL BE PREFACED

BY FACT WILL NOT BE ON SAME CIRCUIT.

2. ASSUME NO OBJECTION TO REGISTRATION IN THEATRE AS

*When ready ?? - talked RGT - SSCS
handling RPS*

TO	
INFO	
WLS	
RCL	
RDS	ISDS

DC/

25X1A 07 JANUARY 1948

SECRET

25X1A

COMOPS FROM

COPY #1 CCB 25X1A
COPY #2 OPS ✓

25X1A

SERVICE MESSAGE

1. RADIOTELETYPE AVAILABLE THIS STATION BUT LACK OF ROOM SPACE PREVENTS CONSTRUCTION OF SUITABLE DIVERSITY ANTENNA SYSTEM AND EQUIPMENT IS SUBJECT TO FITS OF TEMPERAMENT ON POOR OR WEAK SIGNALS THAT WOULD OPERATE EQUIPMENT WITH PROPER ANTENNAS.
2. EQUIPMENT FOR CW CIRCUIT CONSISTS OF SUPERPRO RECEIVERS BC 610 TRANSMITTERS AND BOEHME EQUIPMENT IF NEEDED. BC 399 IS AVAILABLE BUT NOT SET UP IF BC 610 CANNOT PUT SIGNAL INTO BUT PREFER NOT TO TRY AND USE IT SINCE PHYSICAL SETUP WOULD BE AWKWARD.

25X1A